FIELD INSPECTION REPORT

Date of Inspection:	02 hal	
Date of Inspection:	talina.	
Name of the Walterford		
Scheme/Programme:	MARIE Today William Vindo	ingh chank
Package No.: MR/N/20	2-21-Danahurha Dand HAN	er-schoolydet ya
Package No.: MR/N/20-21-Danafaur/12 Road Id No.: Status of the Project: Ongoing/Completed/Under Maintenance Work is a cose of		100
Work is a case of: New Connectivity/Up gradation/ Maintenance		
SE No. Parameters to be checked		
i Pavement	The color of the checked	Remarks
	A CONTRACTOR OF THE PARTY OF TH	
a) Road Junction condition		S/U
b) Condition of Surfacing		S/U
c) Riding Quality		S/U
d) Road Camber		S/U
e) Whether free aggregates in ca	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f) Contraction Join	Contraction Joints provided or not (CC Pavement)	
g) Compaction of f	Compaction of flank/slope & raincuts if any	
2		
a) Condition of head	Condition of head walls in Hume pipe culverts including its painting	
	Condition of Abutment & Wing walls, Slab in RCC culverts	
) Condition of raili	Condition of railings/slab/approach for Bridges	
Road Furniture		
Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
Compliance Histo		
	The state of the s	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

North is not started.

NAME: Nigmanand Mapto 2/12/20

DESIGNATION

(Signature)

DESIGNATION: