FIELD INSPECTION REPORT

Date of	Inspection:	3/12/2020	TION REPORT	
Division	1: DAHAPU	P.	District: PAT.HA	**********
Name o	f the Road:	tar banch on the	Length (km): 1.5856m.	4, 4
	'- rogramme:	MAINTENIANOR	to Tikelibur.	
Packag	e No .: mr - N/19-	20 Jamen to 2	Road Id No.:	
Status (ine Project:	Ongoing/Completed	Under Maintenance	
Work is a case of:		Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance		
Sl. No.		Parameters to 1		Remarks
i.	Pavement			
a)	Road Junction	condition		S/ <i>J</i>
b)	Condition of Surfacing 100m+r			SÆ
c)	Riding Quality		A state of the sta	SA
d)	Road Camber 180mtr			SAY
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/U			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No			Yes/No
4. **	Compliance His	ioiù		
a)	Status of ATR's	& any others		HO

Overall Rating

Satisfactory (S)	ی
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Klone started .

Maria Ci

5. K. Morror A.E. Morror

(Signature)

NAME: Subash change Mys

DESIGNATION:

Sit