

FIELD INSPECTION REPORT

Date of Inspection : 3.12.20	District: Banka
Division : RWD(W) Division Banka-2	Length (km): 1.213
Name of the Road: Chandan Deoghar PWD Rd to Bhanasra	
Scheme/Programme:	MAINTENANCE
Package No.: RM/BANKA/13/0011	Road Id No.: 20703602028
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No ongoing
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ongoing
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U "
c)	Condition of railings/slab/approach for Bridges	S/SRI/U "
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Ongoing
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

☒ Satisfactory (S)	S
☐ Satisfactory but requires Improvement (SRI)	
☐ Unsatisfactory (U)	

Abinay
03/12/2020
(Signature)

NAME: Krishna Kumar Sinha

DESIGNATION: Executive Engineer
RWD Banka-2