

FIELD INSPECTION REPORT

Date of Inspection : 3.12.2020	District: Banka
Division : RWD(W) Division Banka-2	Length (km): 2.75
Name of the Road: Katoriya PWD Road To Chihutgore.	
Scheme/Programme:	MAINTENANCE
Package No.: R17/BA/BAN/19/0005	Road Id No.: 20703602050
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U Ongoing
b)	Condition of Surfacing	S/U " "
c)	Riding Quality	S/U " "
d)	Road Camber	S/U " "
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No Ongoing
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U " "
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U " "
c)	Condition of railings/slab/approach for Bridges	S/SRI/U " "
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No " "
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

<input checked="" type="checkbox"/> Satisfactory (S)	
<input type="checkbox"/> Satisfactory but requires Improvement (SRI)	
<input type="checkbox"/> Unsatisfactory (U)	

(Signature)
03/12/2020

NAME: Krishna Kumar Sinha

DESIGNATION: Executive Engineer
RWD Banka-2