

FIELD INSPECTION REPORT

Date of Inspection: 3/12/2020 District: Mungel
 Division: Khazangpur - Tazangpur Length (km): 4.50 Km.
 Name of the Road: Khazangpur - Tazangpur
 Scheme/Programme: MAINTENANCE ✓ NMP 2018
 Package No.: No. Road Id No.: S.No - 78
 Status of the Project: ☒ Ongoing ☐ Completed ☐ Under Maintenance
 Work is a case of: ☒ New Connectivity ☐ Up gradation ☐ Maintenance ✓

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slabs/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

S. Kumar
 13.12
 (Signature)

NAME: Suresh Kumar
 Assistant Engineer