

FIELD INSPECTION REPORT

Date of Inspection :		03.12.2020		District :		MUNGER	
Division :		Kharagpur - Tarapur		Length (Km) :		2.730 Km	
Name of the Road :		(To) PWD Road Kharagpur - Jamui - Ramnagar (West) (Chhoti - Hathi)					
Scheme/Programme :		MAINTENANCE					
Package No. :				Road Id No. :		SL No 30	
Status of the Project :		Ongoing/Completed/Under Maintenance					
Work is a case of :		New Connectivity/Up gradation/Maintenance					
Sl. No.	Parameters to be checked					Remarks	
1	Pavement						
a)	Road Junction condition					✓S/U	
b)	Condition of Surfacing					✓S/U	
c)	Riding Quality					✓S/U	
d)	Road Camber					✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.					✓Yes/No	
f)	Contraction Joints provided or not (CC Pavement)					✓Yes/No	
g)	Compaction of flank/slope & raincuts if any					✓Yes/No	
2	Cross Drainage						
a)	Condition of head walls in Hume pipe culverts including its painting					S/SRI/U	} NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts					S/SRI/U	
c)	Condition of railings/slab/approach for Bridges					S/SRI/U	
3	Road Furniture						
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained					✓Yes/No	
4	Compliance History						
a)	Status of ATR's & any others					No	

Overall Rating :

Satisfactory (S) ✓	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME : Sukesh Kumar
DESIGNATION : Assistant Eng.

S. Kumar
03.12.2020
(Signature)