

FIELD INSPECTION REPORT

Date of Inspection :	02/12/2020	District:	Munger
Division :	Munger	Length (km):	6.00 k.m
Name of the Road:	Dargapur Bunt to Barmahiya		
Scheme/Programme:	MAINTENANCE	NEW Maint. Policy - 2018	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/S/A
b)	Condition of Surfacing	S/S/A
c)	Riding Quality	S/S/A
d)	Road Camber	S/S/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/A
g)	Compaction of flank/slope & raincuts if any	Yes/A
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/S/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/S/A
c)	Condition of railings/slab/approach for Bridges	S/S/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	Work is just in starting position, material has been dumped by contractor.

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Balmiki Prasad Sinha
NAME:

(Signature) 