

FIELD INSPECTION REPORT

Date of Inspection :	03.12.2020	District :	MUNGER
Division :	Khagazpur - Tarapur	Length (Km) :	2.00 Km
Name of the Road :	Construction of road from Mahimachak to Rangmah Pakar in Mahimachak.		
Scheme/Programme :	MAINTENANCE		
Package No. :		Road Id No. :	SL. No. 46 (NEW)
Status of the Project :	Ongoing/Completed/Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	✓S/U	
b)	Condition of Surfacing	✓S/U	
c)	Riding Quality	✓S/U	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No	
g)	Compaction of flank/slope & raincuts if any	✓Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U	NA.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No	
4	Compliance History		
a)	Status of ATR's & any others	NO-	

Overall Rating :

Satisfactory (S) ✓	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME : Suresh Kumar
DESIGNATION : A.E.

S. K. S. / 03.12.2020
(Signature)