

# FIELD INSPECTION REPORT

Date of Inspection :		03.12.2020		District :		MUNGER.	
Division :		Kharagpur - Tarpur		Length (Km) :		2.600km	
Name of the Road :		PND Kharagpur - Jamui Main Road Bhalua Coal to Chuna Kothi					
Scheme/Programme :		MAINTENANCE					
Package No. :				Road Id No. :		S/No 33. New.	
Status of the Project :		Ongoing/Completed/Under Maintenance					
Work is a case of :		New Connectivity/Up gradation/Maintenance					
Sl. No.	Parameters to be checked			Remarks			
1	Pavement						
a)	Road Junction condition			✓S/U			
b)	Condition of Surfacing			✓S/U			
c)	Riding Quality			✓S/U			
d)	Road Camber			✓S/U			
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			✓Yes/No			
f)	Contraction Joints provided or not (CC Pavement)			✓Yes/No			
g)	Compaction of flank/slope & raincuts if any			✓Yes/No			
2	Cross Drainage						
a)	Condition of head walls in Hume pipe culverts including its painting			✓S/SRI/U		}	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U		NA	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U			
3	Road Furniture						
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained			✓Yes/No			
4	Compliance History						
a)	Status of ATR's & any others			No.			

Overall Rating :

Satisfactory (S) ✓	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME : Sykesh Kumar  
DESIGNATION : A.E.

S. Kumar  
03.12.2020  
(Signature)