

FIELD INSPECTION REPORT

Date of Inspection :	02/12/2020	District:	Munger
Division :	Munger	Length (km):	0.700
Name of the Road:	Daira bagicha se Jagdishpur path		
Scheme/Programme:	MAINTENANCE	M/R - 3054	
Package No.:		Road Id No.:	20803708150
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No S
f)	Contraction Joints provided or not (CC Pavement)	Yes/No S
g)	Compaction of flank/slope & raincuts if any	Yes/No S
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/NA
c)	Condition of railings/slab/approach for Bridges	S/NA/NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	Handwritten notes in Hindi regarding ATR status and other compliance issues.

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

MD. ALI ANWAR
NAME:

(Signature)
02/12/2020