## FIELD INSPECTION REPORT

Date of Inspection:		03.12.2020	District :	MUNGER	
Division :	Klare	PAR-TARAPUT.	Length (Km):	3.130 KM	
Name of t	he Road :	03.12.2020 PMT-TATAPUT .  Constanetin of E	Barataro Gosavo	eit, Breli	Novel to Fassig
Scheme/P	rogramme :	MAINTENANCE			
Package No. :			Road Id No.:	INO.: SUM AS (MEW)	
Status of the Project:		Ongoing/Completed/Unde	ngoing/Completed/Under Maintenance		
Work is a case of :		New Connectivity/Up gradation/Maintenance			
Sl. No.		Parameters to be checked		Remarks	
1	Pavement				
a)	Road Junctio	on condition		VS/U	
b)	Condition of Surfacing		₩S/U		
c)	Riding Quality		√S/U		
d)	Road Cambe	Road Camber			
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			¥es/No	
f)	Contraction Joints provided or not (CC Pavement)			₩Yes/No	
g)	Compaction of flank/slope & raincuts if any			L-Yes/No	
2	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	<u> </u>
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U	NA.	
c)	Condition of railings/slab/approach for Bridges		Bridges	S/SRI/U	1
3		ad Furniture			<u>.</u>
	Whether sign boards/informatory/cautionary board/Km 200m stones/Pavement road markings are provided and maintained			LYes/No	
4	Compliance	History			
a)	Status of ATR's & any others			No,	

Overall Rating:

Satisfacory (S)	
Satisfacory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Ram Darsdan Ram.
DESIGNATION: J.E.

(Signature)