

FIELD INSPECTION REPORT

Date of Inspection:	31/12/2020	District:	Mungel
Division:	Kharagpur Tadarapur	Length (km):	1.250 km
Name of the Road:	Bansipur AWD Road to Dhebaia via Chakdhebaia		
Scheme/Programme:	MAINTENANCE ✓		
Package No.:	N.O.	Road Id No.:	20803808038
Status of the Project:	Ongoing/Completed/Under Maintenance ✓		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓		

Sd. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	No. f.c.c. Yes/No
f)	Contraction Joints provided or not (CC Pavement)	No. f.c.c. Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slabs/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/kin & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N.O.

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Shailendra Kumar

(Signature)

NAME: