FIELD INSPECTION REPORT

		12/20 D	btrict: Jamui	
Division: Jamyi			Length (km): 3.405 Km	
	of the Road:	Amin To Konai		
	ne/Programme:	MAINTENANCE		
	ge No.:		ad Id No .: 208041	01027
Status of the Project: Ongoing/Comp. Work is a case of: New Connective		Ongoing/Completed/Un	der Maintenance	
		New Connectivity/Up gradation/ Maintenance		
		Ratometera in be	heukud	Remarks
1.	Pavement		11.11.11.11.11.11.11.11.11.11.11.11.11.	
a)	Road Junction condition			√87U
b)	Condition of Surfacing			S/U
c)	Riding Quality			√8/U
d)	Road Camber			√8/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			√8/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			√S/SRI/U
c)	Condition of railings/slab/approach for Bridges			√5/SRI/U
3.	Road Furnitur		198645 1974 59	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance H	124.5 12.12.11 1.15.1 1.15.1 1.15.1 1.15.1 1.15.1 1.15.1 1.15.1 1.15.1 1.15.1 1.15.1 1.15.1 1.15.1 1.15.1 1.15		
a)	Status of ATR's	& any others	iph.or	N/A

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: