FIELD INSPECTION REPORT

| Date of | Inspection: 3 | 112/20 | Dhtrict: Janui | |
|----------|--|------------------|--|--|
| DIVISION | 1: Tem | | Langth (lem) | |
| Name of | fthe Road: Na | 4KADIN TO KULL | Length (km): 2.9 Km | |
| Scheme | Programme: | MAINTENANCE | aph Via upri Naukan | road |
| Package | No .: MR - H/ | 19-20 Jami/19 | Road Id No.: | |
| OTRIUS O | the Project: | Ongoing/Complete | d/Under Maintenance | |
| Work is | a case of: | New Connectivity | The mandathanks and series | - |
| Sl. No. | | Satemetera) | | All Harris |
| 1. | Pavement | 4950 | THE PERSON OF TH | |
| a) | Road Junction | condition | THE COURT OF THE C | 8/U |
| b) | Condition of S | urfacing | | |
| c) | Riding Quality | | | ₩8/U |
| | | | | √8/U |
| d) | Road Camber | | | √S/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. Yes/Not | | | Yes/Non A |
| f) | Contraction Joints provided or not (CC Pavement) | | | YesAvon |
| g) | Compaction of flank/slope & raincuts if any | | | Yes/No |
| 2., | Cross Drainag | Q | | To the same of the |
| a) | Condition of head walls in Hume pipe culverts including its painting S/SRI/U | | | ✓S/SRI/II |
| b) | Condition of Abut and Silver | | | √S/SRI/U |
| c) | Condition of railings/slab/approach for Bridges | | | S/SRI/U |
| 3. | Road Furnitur | | | THE RESERVE |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | | | Yes/No |
| 4. | Compliance Hi | Story | CALL TO THE STATE OF THE STATE | |
| a) | Status of ATR's | & any others | | N/A |

Overall Rating

| Satisfactory (S) | < |
|---|---|
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |

103-11 20 C

(Signature)

NAME: