FIELD INSPECTION REPORT

Date of Inspection: 03-12-2020		2020	District: Jamu		
Division: Jhazila			Length (km): 2.53		
Name of the Road:	Dady	our -	Kit Batbajze		
Scheme/Programme:	MAINTENANCE				
Package No.: RMJA	SHA 19	0025	Road Id No.: 20804102046		
Status of the Project:	Ongoing/Completed/Under Maintenance				
Work is a case of:	New Connectivity/Up gradation/ Maintenance				

Slive	Parameters to be checked	Remarks
	Pavement	
a)	Road Junction condition	S/U N/R
b)	Condition of Surfacing	S/U N/A
c)	Riding Quality	S/U N/
d)	Road Camber	₩87 U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No Ne
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	₽8/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a).	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4	Compliance History	1//
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	C	5.
Satisfactory but requires Improvement (SRI)		7
Unsatisfactory (U)		

NAME: Anisus Lahmon
DESIGNATION: Executive Engineer

Elithie Engineer Rural Works Department Works Division, Jhajha