FIELD INSPECTION REPORT

- Maria Carlo			Control of the state of the sta	
Date of Inspection: 03-12-2020			District: Jamu	
Division: Jhazha			Length (km): 2.63	
4	the Road:	Gopal Man		
	Programme:	MAINTENANCE	(New maint, Po	lia)
		19 0008	Road Id No.: 2080410 28	253
Status of the Project:		Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/ Maintenance		
Sl. No.		Parameters to	be checked	Remarks
, K	Pavement			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
a)	Road Junction	condition		_8/Ú
b)	Condition of Surfacing			· 187U
c)	Riding Quality			870
d)	Road Camber			VS/U
е)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Draina	ge		
a)	Condition of head walls in Hume pipe culverts including its painting 8/SRI/U			87SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/U			
c)	Condition of railings/slab/approach for Bridges S/SRI/U			S/SRI/U

Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained

Overall Rating

a)

a)

	Satisfactory (S)	5
•	Satisfactory but requires Improvement (SRI)	- 5%
	Unsatisfactory (U)	

NAME: Arisur Lahman

Road Furniture

Compliance History

Status of ATR's & any others

DESIGNATION: E.E.

(Signature) Engineer
Executive Engineer
Rural Works Department
Works Division. Jhajha

Yes/No