

FIELD INSPECTION REPORT

Date of Inspection : 03-12-2020	District: Tamil
Division : Jhajha	Length (km): 9.48
Name of the Road: Rajla Kund to Kauda	
Scheme/Programme: MAINTENANCE (New maint. policy)	
Package No.: RAJAJHA/19/0015	Road Id No.: 20804102073
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	


Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U N/A
b)	Condition of Surfacing	S/U N/A
c)	Riding Quality	S/U N/A
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	~ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No N/A
4.	Compliance History	
a)	Status of ATR's & any others	S

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Anisur Rahman

DESIGNATION: Executive Engineer


 (Signature)
 Executive Engineer
 Rural Works Department
 Works Division, Jhajha