

FIELD INSPECTION REPORT

Date of Inspection:	9.12.20	District:	Datnang
Division:	2nd District	Length (km):	9.70
Name of the Road:	Repaired road to the sea	Section:	100m
Scheme/Programme:	MAINTENANCE	W/L:	1/18
Package No:		Road Id No:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked		Remarks

1. Pavement		
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of Bankslope & subbase if any	Yes/No
2. Cross Drainage		
a)	Condition of bed walls in flume pipe culverts including its painting	S/S/R/U
b)	Condition of Abutment & Wing walls, Sub in R.C culverts	S/S/R/U
c)	Condition of railing/slabs approach for Bridges	S/S/R/U
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/ken & 200m stones/Pavement road markings are provided and maintained	Yes/No
4. Compliance History		
a)	Status of ATRs & any others	—

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SI)	
Unsatisfactory (U)	U

NAME: _____

DESIGNATION:

(Signature)