

FIELD INSPECTION REPORT

Date of Inspection: 3.12.2014		District: Palani
Division: K. U. D. - Marudathurai		Length (km): 1.25
Name of the Road: Repaired road from Marudathurai to Marudathurai		
Scheme/Programme: MAINTENANCE		1772
Package No.:		
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1. Pavement		
a)	Road Junction condition	S S/U
b)	Condition of Surfacing	U S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flurk/slope & rainouts if any	Yes/No
2. Gross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRU
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRU
c)	Condition of railings/slab/approach for Bridges	S/SRU
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4. Compliance History		
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME:

[Signature]

(Signature)

DESIGNATION:

S. C.

[Signature]

07/12/2014