

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020	District: PURNEA
Division : R.W.D. PURNEA	Length (km): 2.36 Km
Name of the Road: NH 107 - MADHUBAN	
Scheme/Programme: MAINTENANCE	3054 M/R New Maint Policy.
Package No.: 224 MB/19-20	Road Id No.: 21105202138
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1. Pavement		
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U
c)	Condition of railings/slab/approach for Bridges	S/SR/U
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
Compliance History		
a)	Status of ATR's & any others	ND

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

[Signature]
(Signature)

NAME: PANCHANAN MUNDHE.

DESIGNATION: A.C.P. W.D. Purnea Kh.