

FIELD INSPECTION REPORT

Date of Inspection : 3/12/2020	District: Purnia
Division : R.W.D. Div. Purnia	Length (km): 3.1 km
Name of the Road: SH-65 Kotha to Sabarna via Basighat	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	L/S/U
b)	Condition of Surfacing	L/S/U
c)	Riding Quality	L/S/U
d)	Road Camber	L/S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N.B. Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N.B. Yes/No
g)	Compaction of flank/slope & raincuts if any	L/Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	L/S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	L/S/SRI/U
c)	Condition of railings/slab/approach for Bridges	L/S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	L/Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Murali Das

DESIGNATION: J.E

Murali Das
(Signature)