FIELD INSPECTION REPORT

Date of Inspection : 2	. 12. 2-0	District: Puknen	
Division: KWD. DIV PURMEN		Length (km): 2.5 v	
Name of the Road: 30	MALGODY RALLY	MAY GUHTS TO HAHIYAKPIR YIA	
Scheme/Programme:			
Package No.:		Road Id No.: 21105208093	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	No. Parameters to be checked	
1,	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	₹⁄U
d)	Road Camber	S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridges	
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating

Satisfactory (S)	2
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	-

Row Lather 2020 (Signature)

NAME: ROHA SARKAR

designation: J.E