FIELD INSPECTION REPORT

Date of Inspection :	812.20	District: PURHEA
Division: RND. DIV	· PORME A	Length (km): 4.12 km
Name of the Road:	PARPA MH-81	TO KANAIYA
Scheme/Programme:	MAINTENANCE	
Package No.:		Road Id No.: 2110520808
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1,	Pavement	
a)	Road Junction condition	S(U
b)	Condition of Surfacing	
c)	Riding Quality	S/U
d)	Road Camber	S/U/
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b).	Condition of Abutment & Wing walls, Slab in RCC culverts	8/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/Ú
3.	Road Furniture	\$2.0 X
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

1.)

(Signature)

NAME: GAJENDRA PD. HIMANIO

DESIGNATION:] E