

FIELD INSPECTION REPORT		
DATE OF INSPECTION:	03/12/2020	DISTRICT: PURNEA
DIVISION:	DHAMDARA	LENGTH: 2.250 KM
NAME OF THE ROAD:	Smaran Kherachand to Dattu van Lathu Kherachand	
SCHEME/PROGRAMME:	MAINTENANCE	
PACKAGE No:	ROAD ID No.: 2/10530/022	
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE	
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE	
SL.NO	PARAMETERS TO BE CHECKED	REMARKS
1	PAVEMENT	
A	ROAD JUNCTION CONDITION	S
B	CONDITION FO SURFACING	S
C	RIDING QUALITY	S
D	ROAD CAMBER	S
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE FO CC PAVEMENT	Yes
F	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)	N.A
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	Yes
2	CROSS DRAINAGE	
A	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	N.A
B	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	N.A
C	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	N.A
3	ROAD FURNITURE	
A	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED	Yes
4	COMPLIANCE HISTORY	
A	STATUS OF ATR"s & ANY OTHERS	No any ATR
OVERALL RATING		
SATISFACTORY(S)		S
SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)		-
UNSATISFACTORY(U)		-

NAME: Kamal Daryan Sharma.  
DESIGNATION: Junior Engineer.

3/12/2020  
SIGNATURE