

# FIELD INSPECTION REPORT

DATE OF INSPECTION:	03/12/2020	DISTRICT:	Purnea						
DIVISION:	Dhamdaha	LENGTH:	3.157 km						
NAME OF THE ROAD:	Dhamdaha to Magra Tale (mageliya purnadaha)								
SCHEME/PROGRAMME:		MAINTENANCE	MR-3054-HGD						
PACKAGE No:	RM/pv/DHA/19/000/	ROAD ID No.:	21165302028						
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE								
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE								
SLNO	PARAMETERS TO BE CHECKED	REMARKS							
1	PAVEMENT								
A	ROAD JUNCTION CONDITION	S							
B	CONDITION FO SURFACING	S							
C	RIDING QUALITY	S							
D	ROAD CAMBER	S							
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE FO CC PAVEMENT	YES							
F	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)	H.A							
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	YES							
2	CROSS DRAINAGE								
A	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	H.A							
B	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	H.A							
C	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	H.A							
3	ROAD FURNITURE								
A	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED	YES							
4	COMPLIANCE HISTORY								
A	STATUS OF ATR's & ANY OTHERS	No Any ATR							
OVERALL RATING	<table border="1"> <tr> <td>SATISFACTORY(S)</td> <td>S</td> </tr> <tr> <td>SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)</td> <td>-</td> </tr> <tr> <td>UNSATISFACTORY(U)</td> <td>-</td> </tr> </table>			SATISFACTORY(S)	S	SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)	-	UNSATISFACTORY(U)	-
SATISFACTORY(S)	S								
SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)	-								
UNSATISFACTORY(U)	-								

Purnea  
03-12-2020  
SIGNATURE

NAME: Pramad Kumar  
DESIGNATION: JUNIOR-ENGINEER