	FIELD INSPECTION REPORT	
DATE OF INSPECTION:	03/12/2020 DISTRICT: PURTLE	
DIVISION:	Discondate LENGTH: 0.95 Km	
NAME OF THE ROAD:	PIND Road Heursupouli to superuli chaple	
SCHEME/PROGRAMME:	MAINTENANCE MR 13054)-HED	
PACKAGE No:	RM) PU/DH# /19/0017 ROADIDNO :: 21/07302050	
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE	
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE	
SL.NO	PARAMETERS TO BE CHECKED	REMARKS
1	PAVEMENT	
Α	ROAD JUNCTION CONDITION	3
В	CONDITION FO SURFACING	5
c	RIDING QUALITY	
D	ROAD CAMBER	
	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE FO CC PAVEMENT	Yes
E	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)	MYA
F	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	yes
<u> </u>	CROSS DRAINAGE	
	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS	H/H
A	PAINTING PAINTING PAINTING PAINTING PAINTING PAINTING PAINTING	H/ A
В	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	H/4
C	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES ROAD FURNITURE	
3	TO A ROS (IN SORMATORY BOARD/ KM & 200 M	Yes
Α	STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND WARRENCE	
4	COMPLIANCE HISTORY HO Amy ATP	
A	STATUS OF ATR'S & ANY OTHERS	17.4
		1 8
OVERALL RATING	SATISFACTORY(S)	
	SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)	_
	UNSATISFACTORY(U)	

NAME: Arigh Kymas Singh DESIGNATION:

Rural Works Department Works Division, Dhamdaha (Purnea SIGNATURE
EXOCUTIVO ENGINOCI
Rural Works Department
Works Division, Ohamdaha (Purnea