

FIELD INSPECTION REPORT		
DATE OF INSPECTION:	03/12/2020	DISTRICT: Purnea
DIVISION:	Dhanda	LENGTH:
NAME OF THE ROAD:	Lahia Chark Soling Rd. to Purnea Garail	
SCHEME/PROGRAMME:	MAINTENANCE MR -	
PACKAGE No:	ROAD ID No.: 2110308069	
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE	
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE	
SL.NO	PARAMETERS TO BE CHECKED	REMARKS
1	PAVEMENT	
A	ROAD JUNCTION CONDITION	S
B	CONDITION OF SURFACING	S
C	RIDING QUALITY	S
D	ROAD CAMBER	S
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE OF CC PAVEMENT	YES
F	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)	HA
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	YES
2	CROSS DRAINAGE	
A	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	H.A
B	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	HA
C	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	H.A
3	ROAD FURNITURE	
A	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED	YES
4	COMPLIANCE HISTORY	
A	STATUS OF ATR's & ANY OTHERS	NO ANY ATR
OVERALL RATING		
SATISFACTORY(S)		S
SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)		-
UNSATISFACTORY(U)		-

NAME: Pramod Kumar  
 DESIGNATION: JUNIOR-ENGR, Dhanda

P. Kumar  
 03-12-2020  
 SIGNATURE