FIELD INSPECTION REPORT

	f Inspection: 3 12	2020 District: Katihar.	
Divisio	on : Katihar	Length (KM): 3.90 KM	
Name of Road:		Length (KM): 3.90 KM Binodpur panchayout Harihar pur Road To yogira Road from Harish pur	
Scheme/ Programme:		MAINTENANCE	
Packag	ge NOMR-N/19-20	kating 107 Road ID No. 21105501010	
Status of the Project:		Orging/Completed/Under Maintenance	
Work is a case of:		New Connectivity/ Up Gradation/ Maintenance	
Sl.No		Parameters to be Checked	Remarks
1	Pavement		-
a)	Road Junction Condition S/U N		S/U NA
b)	Condition of Surfacing		S/U NA
c)	Riding Quality		S/U NA
d)	Road Camber		S/UNA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		Yes/No N
f)	Contraction Joints provided or not (CC Pavement)		Yes/No N
g)	Compaction of flank/slpoe & raincuts if any		Yes/No po
2	Cross Drainage		
a)	Condition of headwalls inn Humepipe culverts including its painting S/3		S/SRI/U
b)	Condition of Abutment & Wings walls, Slab in RCC culverts		S/SRI/U ↑
c)	Condition of railings/slabs//approach for Bridges		S/SRI/U N
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.		Yes/No
4	Compliance History		
a)	Status of ATR & any others		Нο
Overal	l Grading:	Satisfactory (S)	S
		Satisfactory but requires Improvement(SRI)	
		Unsatisfactory (U)	

Name: Véjay Kumaz Degisnation- A.E. Kalifay

R.W.D. Works Div., Katihar