## FIELD INSPECTION REPORT

Date of I	nspection: 3/12/1	סכס	District: Kati Lar.	
Name of Road:		Mansa	rhi Hat to kursail	
Scheme/ Programme:		MAINTENANCE (New Maintenance policy)		)
Package No. Road ID No.				
Status of	the Project:	Onging/Con	npleted/Under Maintenance	5
Work is a	case of:	New Connec	ctivity/ Up Gradation/ Maintenance	
Sl.No	Parameters to be Checked Remarks			
1-1	Pavement			
a)	Road Junction Condition			.11/4
b)	Condition of Surfacing			NA
c)	Riding Quality			AlA
d)	Road Camber			NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			N/A
f)	Contraction Joints provided or not (CC Pavement)			N/A
g)	Compaction of flank/slpoe & raincuts if any			N/A
2	Cross Drainage			
a)	Condition of headwalls inn Humepipe culverts including its painting			NIA
b)	Condition of Abutment & Wings walls, Slab in RCC culverts			N/A
c)	Condition of railings/slabs//approach for Bridges			N/A
T #20m2903000	Road Furniture			
	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.			NA
4	Compliance History			
a)	Status of ATR & any others			NO
5		Satisfactory Satisfactory Unsatisfacto	but requires Improvement(SRI)	N/A
, (-)				-

Name: Amrendra Nath Trakeur Degisnation Junion Engineer.

(Signature)

Remarks: - week lasn't started due tothdeath of astern agency.