FIELD INSPECTION REPORT

Date o	of Inspection: 03.1	2.2020	District: Katihar.	
Division : Katihar			Length (KM): 6.130 K. M.	
Name of Road:		Duma	vr to Bhangaha Via chtohau	
Schem	ne/ Programme:	MAINTEN.	ANCE	
Packa	ge No.M/R-N/19-20	Kathan/16	Road ID No. NEA 22000855	,
			npleted/Under Maintenance	
Work is a case of: New Conne		New Conne	ctivity/ Up Gradation/ Maintenance	
Sl.No	Parameters to be Checked		ameters to be Checked	Remarks
`1	Pavement			
a)	Road Junction Condition			S/U NA
b)	Condition of Surfacing			S/U NA
c)	Riding Quality			S/U NA
d)	Road Camber			S/U NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement Ye			Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)			Yes/No NA
g)	Compaction of flank/slpoe & raincuts if any Yes/No			Yes/No Pa
2	Cross Drainage			
a)	Condition of headwalls inn Humepipe culverts including its painting S/SRI/U			S/SRI/UNA
b)	Condition of Abutment & Wings walls, Slab in RCC culverts			S/SRI/UNA
c)	Condition of railings/slabs//approach for Bridges			S/SRI/U
3	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.			Yes/No Pars
4	Compliance History			
a)	Status of ATR & any others			NO
Overall	Grading:	Satisfactory	` <u>_</u>	
			but requires Improvement(SRI)	SR1
		Unsatisfacto	ry (U)	

Name: PAPPU KUMAR
Degisnation- J. E. Samelo

R.W.D. Works Div., Katihar

3. (2. 2020 (Signature)