FIELD INSPECTION REPORT

Date o	f Inspection: 3 12	- 2020 District: Katihar.	
	on : Katihar		
Name of Road:		kolasi To semapur Road part 'A'	
Scheme/ Programme:		MAINTENANCE	
Package No.		Road ID No. 21105508079	
Status of the Project:		Onging/Completed/Under Maintenance	
Work is a case of:		New Connectivity/ Up Gradation/ Maintenance	
Sl.No		Parameters to be Checked	Remarks
1	Pavement		
a)	Road Junction Cond	_8/U	
b)	Condition of Surfac	∠S/U	
c)	Riding Quality	√S/U	
d)	Road Camber		⊸8/U
e)	Whether free from of Pavement	Yes/No NA	
f)	Contraction Joints p	Yes/No N A	
g)	Compaction of flank/slpoe & raincuts if any		Yes/No NA
2	Cross Drainage		
a)	Condition of headwalls inn Humepipe culverts including its painting		
b)	Condition of Abutn	S/SRI/U N	
c)	Condition of railings/slabs//approach for Bridges		S/SRI/U N
3	Road Furniture		
a)	Whether sign board road markings are p	Yes/No	
4	Compliance History		
a)	Status of ATR & any others		NO
Overall Grading:		Satisfactory (S)	S
		Satisfactory but requires Improvement(SRI)	7
		Unsatisfactory (U)	

Name: Dilip kumar Degisnation- Junior enginper

R.W.D. Works Div., Katihar