FIELD INSPECTION REPORT

f Inspection: 3 12	District: Katihar. Lpngth - 3	.20 KM
of Road:	Chandwa Rupaspur Upto Kamailep pancha	
e/ Programme:	MAINTENANCE	
ge No.MR-N /19-20k	Athar/07 Road ID No. 21105602015	
of the Project:	Onging Completed/Under Maintenance	
is a case of:	New Connectivity/ Up Gradation/ Maintenance	
	Parameters to be Checked	Remarks
Pavement		
Road Junction Condition		S/U NA
Condition of Surfacing		S/U NA
Riding Quality		S/U NA
Road Camber		S/U NA
Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		Yes/No NA
Contraction Joints provided or not (CC Pavement)		Yes/Non A
Compaction of flank/slpoe & raincuts if any		Yes/No ban
Cross Drainage		
Condition of headwalls inn Humepipe culverts including its painting		S/SRI/U N
Condition of Abutment & Wings walls, Slab in RCC culverts		S/SRI/U N
Condition of railings/slabs//approach for Bridges		S/SRI/U N
Road Furniture		
Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.		Yes/No par
Compliance Histor	у	
Status of ATR & any	y others	No
Overall Grading:	Satisfactory (S)	5
	Satisfactory but requires Improvement(SRI)	
	Unsatisfactory (U)	
	e/ Programme: ge No.MR-N/19-20k of the Project: is a case of: Pavement Road Junction Cond Condition of Surface Riding Quality Road Camber Whether free from of Pavement Contraction Joints p Compaction of flank Cross Drainage Condition of Abutin Condition of railings Road Furniture Whether sign boards road markings are pi Compliance Histor Status of ATR & any	MAINTENANCE Se No.MR-N/19-20/20/20/20/20/20/20/20/20/20/20/20/20/2

Name: CHANDRAHAS KUMAR

Degisnation-

Executive Engineer, R.W.D. Works Div., Katihar

(Signature)