FIELD INSPECTION REPORT

Date of Inspection: 03-12-2020			District: Kishongang'	
Division: Kishangeryi-I		y`-I	Length(km): 4.330	
Name o	of the Road: Bh	100 ha - Rassape	N.c. ·	
Scheme/Programme: MAINTENANCE		MAINTENANCE		
Package No.: RM KI		KIS 19 0004 Road Id No .: 21205802021		
Status of the Project:		Congoing/Completed /Under Maintenance		
Work is	a case of:	New Connectivi	ity/ Up gradation / Maintenance	
\$1. No	Parameters to be checked		Remarks	
1.	Pavement			S/U
a)	Road Junction	Condition —	s/U	
b)	Condition of Su	ırfacing	ook not start yet.	S/U
c)	Riding Quality			S/U
d)	Road Camber			€ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints Provided or not (CC Pavement) - M·A			Yes/No
g)	Compaction of fland / shop & raincuts if any			~Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its Painting			S/SRI/U
b)	Condition of Al	ion of Abutment & Wing walls, slab in RCC culverts		
c)	Condition of railings/Slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No			Yes/No
4.	Compliance His	story		Sound
a)	Status of ATR's	& any others	ATR not s	endize.

Overall Rating:

S
_
_

J.E RWD tehagachh.

(Signature)

NAME: