## FIELD INSPECTION REPORT

| Date of                  | f Inspection: 02  | -12-20          | District: - Kishanganj            |         |  |
|--------------------------|---|-----------------|-----------------------------------|---------|--|
| Division: - kighangany-s |   |                 | Length(km): 1.25 KM               |         |  |
| Name o                   | of the Road: This   | myakatta pmo    | 954 TO Thingsterning taufir Road  |         |  |
| 9                        |   | MAINTENANC      | ANCE                              |         |  |
| Packag                   | e No .: MR-N119   | 1-20/Kishampanj | * 165 Road Id No .: 212059 01001  |         |  |
|                          |   |                 | Completed /Under Maintenance      |         |  |
| Work is                  | a case of:  | New Connect     | ivity/ Up gradation / Maintenance |         |  |
| S1. No                   |   | Paramete        | ers to be checked                 | Remarks |  |
| 1.                       | Pavement  |                 |                                   | S/U     |  |
| a)                       | Road Junction   | Condition       |                                   | € S/U   |  |
| b)                       | Condition of Surfacing  |                 | work Not started yet              | ∞ S/U   |  |
| c)                       | Riding Quality  |                 |                                   | · S/U   |  |
| d)                       | Road Camber   |                 |                                   | S/U     |  |
| e)                       | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.  |                 | Yes/No                            |         |  |
| f)                       | Contraction Joints Provided or not (CC Pavement) N · A  |                 |                                   | Yes/No  |  |
| g)                       | Compaction of fland / shop & raincuts if any NOT stented  |                 |                                   | Yes/No  |  |
| 2.                       | Cross Drainage  |                 |                                   |         |  |
| a)                       | Condition of head walls in Hume pipe culverts including its Painting S/SRI/U  |                 |                                   |         |  |
| b)                       | Condition of Abutment & Wing walls, slab in RCC culverts * S/SRI/U  |                 |                                   |         |  |
| c)                       |   |                 |                                   | S/SRI/U |  |
| 3.                       | Road Furniture  |                 |                                   |         |  |
| a)                       | Whether sign boards/informatory/cautionary Board/km & 200m  Yes/No stones/Pavement road markings are provided and maintained why imported and maintained with the stones of the stones. |                 |                                   |         |  |
| 4.                       | Compliance History  |                 |                                   |         |  |
| a)                       | Status of ATR'  | s & any others  | NO ATR                            | pending |  |

Overall Rating :

| Satisfactory(S)                             | 7 |  |
|---|---|--|
| Satisfactory but requires Improvement (SRI) |   |  |
| Unsatisfactory(U)                           | - |  |

work delayed

02.12.20

(Signature)

NAME: Err. Radheshyam progjapati