FIELD INSPECTION REPORT Date of Inspection: 03-12-2020. Kishangani Division: District: Klishangani - 2 Length (km): 3.15 Name of the Road: L025 to Padempus Scheme/Programme: MAINTENANCE. Package No.: Road Id No.: Status of the Project: Ongoing/Completed/Under Maintenance Work is a case of: New Connectivity/Up gradation/ Maintenance Remarks Sl. No. Parameters to be checked 1. Pavement S/U a) Road Junction condition S/U b) Condition of Surfacing S/U c) Riding Quality S/U. d) Road Camber Whether free from defects such as visible cracks, exposed Yes/No . e) aggregates in case of CC Pavement. Yes/No Contraction Joints provided or not (CC Pavement) f) Yes/No Compaction of flank/slope & raincuts if any g) Cross Drainage 2. Condition of head walls in Hume pipe culverts including its painting S/SRI/U a) Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/U b) Condition of railings/slab/approach for Bridges S/SRI/U c) Road Furniture 3. Whether sign boards/informatory/cautionary Board/km & 200m Yes/No stones/Pavement road markings are provided and maintained a)

Overall Rating

a)

Compliance History

Status of ATR's & any others

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

3/1/20

(Signature)

Berg

NAME: