FIELD INSPECTION REPORT

vace of th	spection:	2 1110	17.11		
division:	1201	12020	District: Nalanda.		
ame of	he Rondi Sh	Sharif	Length (km): S.TID K.M.		
icheme/l'	rogramme:	MADITIO DO	Length (km): 5.710 K.N. Michael Via Bartachael D	wawan	Nθ
W- 1	* ****	MAINTENANCE			
Status of the Project: Ongoing/Completed			Road Id No.:		
Vork is a	case of:	Ongoing/Completed	/Under Maintenance		
S1. No.	Parameters to be checked Remarks				
1.	Parameters to be checked Remarks Pavement				
n)	Road Junction condition S/U				
b)	Condition of Surfacing				ł
c)				S/U	Į١
	Riding Quality			S/U	
d)	Road Camber			S/U	١
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	1
0	Contraction Joints provided or not (CC Pavement)			Yes/No	٦
g)	Compaction of flank/slope & raincuts if any			Yes/No	٦
2	Cross Drains	ige .			14.3
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	_
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	_
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
第2. 形型	Compliance History		10000		
a)	Status of ATR's & any others				_
Overall P	Lating :				_
		Satisfactory (S)		79-14-	_
		Satisfactory but	requires Improvement (SRI)		_
		Unsatisfactory (U			-

NAME: Meliceth Eadous

* Road Taken In PMQ14-III

DESIGNATION: J.E.

Scanned with CamScanner