## FIELD INSPECTION REPORT

rate of In	spection: Ophologo		
division:	O V Districts Moderate	2 1 11	
iame of t	he Romb Length (km): a 265 Kell		
icheme/l	rogramme To 2 To Pakalpub		
ackage [	No.:		
Status of	the Projects   Ownit of Road Id No.:		
Work is a	The state of the s		
SI. No.	Parameters to be checked	Remarks	
1.	Pavement	Keman	
n)	Road Junction condition	S/U (	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U 🔏	
(ل	Road Camber	S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	11
g)	Compaction of flank/slope & raincuts if any	Yes/No	_
2	Cross Drainage		work Not
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	Just wed
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	Storn
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200r stones/Pavement road markings are provided and maintained	n Yes/No	
整体	Compliance History ~ .	1	70 may 19
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

(Signature)

NAME:

Mukesh Eaday

DESIGNATION:  $\mathcal{J} \in \mathcal{A}$ 

Scanned with CamScanner