FIELD INSPECTION REPORT

Date of Inspection: 03/12/2020			District: Arcynla		
Division: Arana			Length (km): 2.420 km.		
Name of	C I T T T T T T T T T T T T T T T T T T	nahalgown o	to Kolabari		
	/Programme:	MAINTENANCE			
Package No.:			Road Id No.: 212.06608109		
	f the Project:		ed/Under Maintenance		
	Vork is a case of: New Connectivity/Up gradation/ Maintenance				
Sl. No.	Parameters to be checked			Remarks	
1.	Pavement				
a)	Road Junction condition			√S/U	
b)	Condition of Surfacing Pot holes (Minar) due to flood			S/U_	
c)	Riding Quality			√S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any Raineut			VYes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			NAS/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Repoint			Yes/No	
4,	Compliance History				
a)	Status of ATR's & any others				

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

TRIBHUWAN MATH

Ranged Kr Mande

M03/12/2020 (Signature)