

FIELD INSPECTION REPORT

Date of Inspection : 02.12.2020	District: Satna
Division : Sonpur	Length (km): 0.730 K.M.
Name of the Road: NH-19 Rasulpur to Ganganadi	
Scheme/Programme: MAINTENANCE	
Package No.: MR-N/19-20-Sonpur/19	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	July 2018

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No - N.A.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No - N.A.
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U - N.A.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U - N.A.
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	Nil

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

DESIGNATION:

(Signature)
 Executive Engineer
 Rural Works Department
 Work Division, Sonpur