FIELD INSPECTION REPORT

Di			District:		rsan
		hypra-1 I	ength (km):	2.321	
Name of the Road: Sasty par to Metankpuz Via Elkdery: Scheme/Programme: MAINTENANCE MR 3054				24	
Package No.:					2 - 0
Status of the Project: Ongoing/Completed			/Under Maintenance		
Work is a case of: New		New Connectivity/Up g	lew Connectivity/Up gradation/ Maintenance		
Sl. No.		Parameters to be checked Remarks			
1.	Pavement			Comment.	Remarks
a) Road Junction		condition		\S/U	
b)	Condition of S	Condition of Surfacing			S/U
c)	Riding Quality	•			\S/U
d) Road Camber					_8/U
e)	Whether free from defects such as visible crac aggregates in case of CC Pavement.		cks, exposed	Yes/No	
f)	Contraction Joi	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No∿		
	Cross Drainage				
)	Condition of hea	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
) .	Condition of Ab	Condition of Abutment & Wing walls, Slab in RCC culverts		verts	8/SRI/U
- 1	Condition of railings/slab/approach for Bridges		S/SRI/U		

Overall Rating

Compliance History

Status of ATR's & any others

a)

4.

a)

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

DESIGNATION:

Whether sign boards/informatory/cautionary Board/km & 200m

stones/Pavement road markings are provided and maintained

Yes/No