

FIELD INSPECTION REPORT

Date of Inspection : 3/12/2020 District: Nalando
 Division : Rajgir Length (km): 2.00 km
 Name of the Road: Const. of Road from Katarikhetpur PMHSY Rd. to CRPF Camp Rajgir Rd.
 Scheme/Programme: MAINTENANCE (3054 mR)
 Package No.: Batch RM/NA/RAJ/19/0002 Road Id No.: 10200604024
 Status of the Project: Ongoing Completed Under Maintenance Ongoing
 Work is a case of: New Connectivity Up gradation Maintenance Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	✓
a)	Road Junction condition	✓ SI
b)	Condition of Surfacing	✓ SI
c)	Riding Quality	✓ SI
d)	Road Camber	✓ SI
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes No (NA)
f)	Contraction Joints provided or not in CC Pavement	Yes No (NA)
g)	Compaction of flank slope & cut outs if any	Yes No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its parapets	S SRI (NA)
b)	Condition of Abutment & Wing walls in RCC culverts	S SRI (NA)
c)	Condition of railings slip approach for Bridge	S SRI (NA)
3.	Road Furniture	
a)	Whether sign boards informative cautionary Board km & 200m stones Pavement road markings are provided and maintained	Yes No (Work in progress)
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

S

Ramprevesh kumar

NAME: SE
Rajgir

3/12/2020
(Signature) JE