

# FIELD INSPECTION REPORT

Date of Inspection: 03.12.2020

District: SARAN

Division: SONPUR

Length (km): 4.100

Name of the Road: BASAUTI TO BHIMA BANDH

Scheme/Programme: MAINTENANCE

Package No :

Road ID No :

Status of The Project: Completed

Work is a case of : Maintenance


Sl.No	Parameters to be checked	Remarks
1	<b>Pavement</b>	
a)	Road Junction Condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	YES
f)	Contraction Joints provided or not (CC Pavement)	YES
g)	Compaction of Flank/slope & raincuts if any	YES
2	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe Culverts including its painting	S
b)	Condition of Abutment & Wing Walls, Slab in RCC Culverts	S
c)	Condition of railings/slab/approach for Bridges	S
3	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	YES
4	<b>Compliance History</b>	
a)	Status of ATR's any others	NO


Overall Rating :

Satisfactory (S)	Satisfactory
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME : SUBHASH RAI  
DESIGN : SUPERINTENDING ENGINEER

NAME:- RAJEEV RANJAN KUMAR  
DESIGNATION: JUNIOR ENGINEER  
PARS A

  
Signature SE/chh9889

  
03/12/20  
RC