

FIELD INSPECTION REPORT

Date of Inspection :	3/12/2020	District:	SIWAN
Division :		Length (km):	3.50 KM
Name of the Road:	DUDHA TO BASANTPUR via Laukipur-fak.		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing <input checked="" type="checkbox"/> Completed <input type="checkbox"/> Under Maintenance <input type="checkbox"/>		
Work is a case of:	New Connectivity <input type="checkbox"/> Up gradation <input checked="" type="checkbox"/> Maintenance <input type="checkbox"/>		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U S
b)	Condition of Surfacing	✓ S/U S
c)	Riding Quality	✓ S/U S
d)	Road Camber	✓ S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuis if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	Nil

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Saurav
3/12/2020
jt
(Signature)

NAME: Saurav Kumar