

FIELD INSPECTION REPORT

| Date of Inspection : 02/12/2020 | | District: Nalanda | |
|---|--|----------------------|-----|
| Division : Bihar Sharif | | Length (km): 1.90 km | |
| Name of the Road: Benar - Saksho Path se Nanaur | | | |
| Scheme/Programme: MAINTENANCE | | | |
| Package No.: | | Road Id No.: | |
| Status of the Project: Ongoing/Completed/Under Maintenance | | | |
| Work is a case of: New Connectivity/Up gradation/ Maintenance | | | |
| Sl. No. | Parameters to be checked | Remarks | |
| 1. | Pavement | | |
| a) | Road Junction condition | S/U | S |
| b) | Condition of Surfacing | S/U | U |
| c) | Riding Quality | S/U | S |
| d) | Road Camber | S/U | S |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | Yes/No | NA |
| f) | Contraction Joints provided or not (CC Pavement) | Yes/No | |
| g) | Compaction of flank/slope & raincuts if any | Yes/No | yes |
| 2. | Cross Drainage | | |
| a) | Condition of head walls in Hume pipe culverts including its painting | S/SR/U | |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | S/SR/U | NA |
| c) | Condition of railings/slab/approach for Bridges | S/SR/U | |
| 3. | Road Furniture | | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No | |
| 4. | Compliance History | | |
| a) | Status of ATR's & any others | -No- | |

Overall Rating :

| | |
|---|-----|
| Satisfactory (S) | S |
| Satisfactory but requires Improvement (SRI) | SRI |
| Unsatisfactory (U) | |

(Signature) 02/12/20

NAME: Mukesh Yadav

DESIGNATION: J.E.