

FIELD INSPECTION REPORT

| Date of Inspection : 02/12/2020 | | District: Nalanda |
|---|--|-----------------------|
| Division : Bihar | | Length (km): 3.700 km |
| Name of the Road: Bihari To Baid (SH 78) Fair | | |
| Scheme/Programme: MAINTENANCE | | |
| Package No.: | | Road Id No.: |
| Status of the Project: Ongoing/Completed/Under Maintenance | | |
| Work is a case of: New Connectivity/Up gradation/ Maintenance | | |
| Sl. No. | Parameters to be checked | Remarks |
| 1. | Pavement | |
| a) | Road Junction condition | S/U |
| b) | Condition of Surfacing | S/U |
| c) | Riding Quality | S/U |
| d) | Road Camber | S/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | Yes/No |
| f) | Contraction Joints provided or not (CC Pavement) | Yes/No |
| g) | Compaction of flank/slope & raincuts if any | Yes/No |
| 2. | Cross Drainage | |
| a) | Condition of head walls in Hume pipe culverts including its painting | S/SRI/U |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | S/SRI/U |
| c) | Condition of railings/slab/approach for Bridges | S/SRI/U |
| 3. | Road Furniture | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No |
| 4. | Compliance History | |
| a) | Status of ATR's & any others | No |

Road damaged during flood 2019
Temporary Restoration work done.

Overall Rating :

| | |
|---|--|
| Satisfactory (S) | |
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |

NR

(Signature)

NAME: Mukesh Yadav

DESIGNATION: J.B.