FIELD INSPECTION REPORT

ate of la	spection:	03-02-2000	District:	SIN	O.A.	
Division :		Siwan-01	Length (km):			Many of the forest the second of the second
	the Road:		e Aadampus			hi
	rogramme:	MAINTENANCE	mR-3054			The confidence of the second of the confidence o
'ackage			Road Id No.:		Polymorphis primate the Participation of	constitution of a large field of the same of the same
Marie Control of the Control of the Control	the Project:	A STATE OF THE PARTY OF T	d/Under Maintenanc			the many or the second second second second second second
	a case of:	New Connectivity/	Up gradation/ Maint	enance		
SI. No.		Parameters to	o be checked		- 1 y	Remarks
1.	Pavement					
a)	Road Junction condition				2 UNE &	
b)	Condition of Surfacing				and the second s	
c)	Riding Quality					US/US
	And the second s					SUS
d)	Road Camber					SIU S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.					
(f)	Contraction Joints provided or not (CC Pavement) Yes/No					
g)	Compaction of flank/slope & raincuts if any					Yes/No ##
2.	Cross Drainage					
a)	Condition of head walls in Hume pipe culverts including its painting SSRI/U S					
b)	Condition of Abutment & Wing walls, Slab in RCC culverts					S/SRI/U Net
c)	Condition of railings/slab/approach for Bridges				S/SRL/U N	
3.	Road Furni	ture	and the state of t	The said of the sa	deleteración es la literación deleteración es con	and the second s
2)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained					Vies/Noxes
4.	Compliance History					100
a)	Status of ATR's & any others				NO ATR	
Owani	Dating	The second secon	The second section of the sect		The Chapter of the Control	American agreement and a second
Overail	Rating	Satisfactory (S	The second section of the second seco			5
		Satisfactory by	Satisfactory but requires Improvement (SRI)			
		Unsatisfactory	Unsatisfactory (U)			

(Signature)

NAME: CHANDAN KUMAR Junion Engineer