FIELD INSPECTION REPORT

Date of	-		TION KEPORT			
Distate	te of Inspection: 3 12/20 District: Natanda					
Name	Ohision: Biharsharif Length (km): 1.90 km					
the Kond: Sara Alana Cara Bisha						
Ingramme: MAINTENANCE						
Package No.: Road Id No.:						
Status of the Project: Ongoing/Completed/Under Maintenance Comple						
The state of the later of the l				ntenance		
SI. No.	Parameters to be checked Remai			Remarks		
1.	Pavement					
a)	Road Junction condition			S/U	S	
b)	Condition of Surfacing			S/U	2	
c)	Riding Quality			S/U	ک	
d)	Road Camber			S/U	2	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	l H NA	
Ŋ	Contraction Joints provided or not (CC Pavernent)			Yes/No	À ′ ′ ′	
g)	Compaction of flank/slope & raincuts if any			Yes/No 1	SIY10	
2	Cross Drainage					
a)	Condition of head walls in Hume pipe culverts including its painting			s/sri/u	S	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	15	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	3	
3.	Road Furnitu	ire			14	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			n Yes/No	Ya.	
1.4.De	Compliance History			La destruction	42 AM	
a)	Status of ATR's & any others		NA			

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Bijay lumer DESIGNATION: Executive engineer