

FIELD INSPECTION REPORT

Date of Inspection :	03/12/2020	District:	Sewan
Division :	Sewan - 1	Length (km):	3.40 km.
Name of the Road:	Madhopur to Surahiya		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A
f)	Contraction Joints provided or not (CC Pavement)	N/A
g)	Compaction of flank/slope & raincuts if any	In Progress
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A
c)	Condition of railings/slab/approach for Bridges	N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Ticked Item Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	151
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

Pawan Kr Verma

DESIGNATION:

Asst Engineer

(Signature)