

**FIELD INSPECTION REPORT**

Date of Inspection : 02/12/20		District: SIWAN
Division : SIWAN-2		Length (km): 2.50 Km
Name of the Road: 2026 - Nautan to Kurmanta		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.:
Status of the Project:		Ongoing/Completed/Under Maintenance ongoing
Work is a case of:		New Connectivity/Up gradation/ Maintenance Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition S	S/U
b)	Condition of Surfacing S	S/U
c)	Riding Quality S	S/U
d)	Road Camber S	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. N/A	Yes/No
f)	Contraction Joints provided or not (CC Pavement) N/A	Yes/No
g)	Compaction of flank/slope & raincuts if any In progress	Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting In progress	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts N/A	S/SRI/U
c)	Condition of railings/slab/approach for Bridges N/A	S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained In progress	Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

DESIGNATION:

20/12/20  
A.E.

20/12/20  
नामपालक अधिकारी  
मौखिक कार्य विभाग  
प्रमुख निवासी

20/12/20  
J.E.  
(Signature)