


FIELD INSPECTION REPORT

Date of Inspection : 03.12.2020	District: Gopalganj
Division : Holhua	Length (km): 1.250 km
Name of the Road: Sabaya to Badheyg Road.	
Scheme/Programme: MAINTENANCE	
Package No.: -	Road Id No.: /
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U 'U'
b)	Condition of Surfacing	S/U 'U'
c)	Riding Quality	S/U 'S'
d)	Road Camber	S/U 'S'
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No - Yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U - N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U - N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No N/A
4.	Compliance History	U
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U


03/12/2020
(Signature)

NAME: ASHOK KUMAR
DESIGNATION: B.B. RWI Div